

EC REP

59-83 Vittoria Street, Birmingham, B1 3NZ, UK

Cookson Driithout BV

Keienbergweg 12 1101 GB Amsterdam

Device Name: Matticraft 75+

Device Type: Pale Yellow – High Strength General Purpose Bonding Alloy

Indications: TYPE 4: For appliances with thin sections that are subject to very

> high forces, e.g. removable partial dentures, clasps, thin veneered single crowns, full arch fixed dental prostheses or those with small cross-sections, bars, attachments, implant retained superstructures.

Free from Be, Cd, Ni, Si and C.

Intended Use: Fabrication of custom-made dental restorations

Intended Patients: Any (no restriction on patient characteristics)

Intended Users: Dental laboratory technicians.

There are no specific contraindications, warnings, or precautions for patients, though see composition if patient allergies are known or suspected.

There are no special storage requirements for this material.

	g
LOT	
REF	ZCA 000

Technical Data

Density	16.1 g/cm³
Composition	Au 75.0%
	Pd 11.7%
	Ag 10.0%
	Sn 1.5%
	In 1.8%
	Others <1.0%
Melting Range	1160 - 1200°C
Elongation	25% After simulated
0.2% Proof Stress	570MPa porcelain firing
Coefficient of Thermal	14.5 x 10 ⁻⁶ K ⁻¹ (25 - 500°C)
Expansion	14.7 x 10 ⁻⁶ K ⁻¹ (25 - 600°C)
Casting Temperature	1350°C
Casting Ring Pre-Heat	850°C for 40 minutes.
Solders: Pre-Bonding	Mattiflo 1025Y Tenacity 125
Flux: Post-Bonding	Mattiflo 715Y
Typical Applications	Single unis, Multiple units
	Long spans
Typical Porcelains	Vita VMK, Doric Universal
	Shofu Vintage

Additional Information

Disposal / Re-Use Considerations: Clean scrap can be reused to make further restorations, however alloys that have been used on patients should not be reused to minimize contamination risk. Once appropriately cleaned, precious metal alloys may be sent

for recycling.

In the event of a defective device

Contact Cooksongold on +441212338170.

If the defect has only become apparent after the alloy has been used on a patient, then also contact the competent authority of the Member State in which the patient is

established (refer to

https://ec.europa.eu/health/md_sector/contact_en)

Summary of Safety and Clinical Performance (SSCP) The Summary of Safety and Clinical Performance (SSCP) is available on request and can also be found at https://ec.europa.eu/tools/eudamed by searching for the Basic UDI-DI 5057531 ALLOYTL (when the website is

operational).

DIRECTIONS FOR USE

WAXING

A minimum wax thickness of 0.3 mm for single crowns and 0.5 mm for multiple units is recommended. The connection area of abutments must be greater than 3 mm x 3 mm. Sprue each unit individually with 3 mm wax rods. Reservoir bars should be a minimum of 4 mm in diameter and vent rods 1 mm if used. Avoid sharp joints and ensure all shoulders and edges are well rounded. Stress relieve the wax pattern by immersing it in water at 32 °C for 5 - 10 minutes.

INVESTMENT

Only use suitable high temperature investment powders that are described as graphite or carbon free. Invest the wax pattern according to the manufacturer's instructions.

BURN OUT AND PRE - HEAT

Follow normal procedures for wax burn out and then heat the investment according to the manufacturer's instructions. Heat soak the casting ring for a minimum of 40 minutes at 850°C. This should be increased to 900 °C for small castings. Time necessary to successfully heat soak the casting ring increases with size.

CASTING

Always melt MATTICRAFT 75+ in ceramic crucibles.

Clean scrap may be reused provided a minimum of 50% new metal is in the charge. NEVER reuse metal if contamination with carbon or other alloys is suspected. A little Tenacity 125 flux added to the melt immediately before casting will improve overall cleanliness but should be avoided if possible. Ensure the alloy is fully liquid and spinning before casting. The time taken to reach both melting and casting temperature must be kept to a minimum and the alloy cast promptly. Over heating the metal results in miscasts and porosity. If using an oxy-propane torch to melt the metal, the flame must be correctly adjusted to avoid contamination by carbon.

Allow the castings to bench cool. $\underline{\bf DO~NOT}$ quench the metal as this may cause fitting problems later on.

CLEANING

Break out the metal and clean by brushing or by sand blasting with non-recycling aluminium oxide. Prepare the surface of the metal with pink or brown stones kept solely for use on **MATTICRAFT 75+**.

Use of worn diamond stones or those used for other alloys causes bonding problems due to contamination.

Finally clean the castings in steam, acetone or by ultrasonic cleaner This alloy is suitable for attachment work and can be lightly milled.

The use of strong acids such as HF is not advised.

DEGASSING AND OXIDATION

All metals absorb gas when liquid. This can be removed by heating the castings in vacuum to 960 $^{\circ}$ C for three minutes. Oxidisation is carried out by further heating at 960 $^{\circ}$ C for 5 minutes in air

Correctly oxidised, **MATTICRAFT 75+** should have a uniform light grey / white colour. Opaque washes can either be applied to the oxide surface or for lighter colours, the oxide layer can be removed by blating with 125 non recycling aluminium oxide powder.

The castings should always be cleaned in hot water or by ultrasonic cleaner prior to the porcelain being applied.

PORCELAIN APPLICATION

Porcelain application should be carried out as specified by the supplier and with consideration to the furnace used. We recommend regular purging and calibration of the furnace along with suitable support for long bridges.

MATTICRAFT 75+ requires a long cooling cycle after porcelain firing.

SOLDERING

Where possible work should be planned to avoid the use of solder. I soldering is required, Mattiflo 1025Y can be used before porcelain application and Mattiflo 715YW for post soldering.

Caution: Suitable protective clothing and the wearing of safety glasses is recommended when melting this product.